U.S. DEPARTMENT OF LABOR Occupational Safety and Health Administration

Form Approved OMB No. 44-R1387

MATERIAL SAFETY DATA SHEET

Required under USD Shipbuilding, i	L Safe and Sh	ty and Hi ipbreakin	salth Regulations for Ship Repairing, g (29 CFR 1915, 1916, 1917)			
	SECTION I March 1980					
MANUFACTURER'S NAME				EMERGENCY TELEPHONE NO.		
Raychem Corporation			(415) 329-333	(415) 329-3333		
ADDRESS (Number, Street, City, State, and ZIP Co 300 Constitution Drive, Menlo CHEMICAL NAME AND SYNONYMS	ode) Par	k, CA.	94025 TRADE NAME AND SYNONYMS S-1006			
HEMICAL FAMILY			Proprietary			
2 Part Epoxy Adhesive						
SECTION	<u> </u>	····	DOUS INGREDIENTS		TLV	
PAINTS, PRESERVATIVES, & SOLVENTS	*	(Units)	ALLOYS AND METALLIC COATINGS	*	(Units)	
PIGMENTS			BASE METAL			
CATALYST Polyamide			ALLOYS			
VEHICLE			METALLIC COATINGS			
	_		FILLER METAL PLUS COATING OR CORE FLUX			
ADDITIVES	_		OTHERS			
	+	 	NO WAS TO BE			
OTHER\$			OUIDS, SOLIDS, OR GASES	*	TLV (Units)	
	OTIO	A. 111	PHYSICAL DATA			
		N III -	SPECIFIC GRAVITY (H20=1)			
BOILING POINT (°F.)			PERCENT, VOLATILE			
VAPOR PRESSURE (mm Hg.)	-	NIL	BY VOLUME (%) EVAPORATION RATE			
VAPOR DENSITY (AIR+1)			(=1)		AIL	
SOLUBILITY IN WATER		NIL	<u> Alexanderia de la companya de la c</u>			
APPEARANCE AND ODOR Viscous lig	uids	- Resi	n purple. Catalyst tan			
SECTION IV	- FII	RE AND	EXPLOSION HAZARD DATA			
FLASH POINT (Method used) Resin 480°F, Catalyst 365°F.				16.	Uel	
EXTINGUISHING MEDIA Class A, B, or C Extinguishe SPECIAL FIRE FIGHTING PROCEDURES None	rs.	Water.				
UNUSUAL FIRE AND EXPLOSION MAZARD						
					n OSHA	

(Continued on reverse side)

Rev. May 72

	\$E	CTION	V - HEAI	TH HAZARD DA	ATA
THRESHOLD LIMIT	VALUE				
Not Establi	xposure		1 : 6	Lleved Conta	ins enoxy and amine resins.
Chin and av	e irritant.	Harmiu	<u>l 11 SWa.</u>	not take inter	ins epoxy and amine resins.
					1
For skin, V	rast AID PROCEDU	areas	with soa	o and water.	If taken internally, induce
vomiting.	Call a physic	cian im	mediatel	y. If in cont	act with eyes, flush with
plenty of v	vater.			,	
		SECTIO	ON VI - R	EACTIVITY DAT	rA
TABILITY	UNSTABLE		CONDITIO	S TO AVOID	
	STABLE	X			
INCOMPATABILITY	Marajale to avoid		<u> </u>		
Acids bas	es, strong ox	10121112	g agents.		
Not determ	ined.			CONDITIONS TO	AVOID
HAZARDOUS	MAY DCCU	R		COMBINATION	
POLYMERIZATION	WILL NOT	OCCUR	X		
	SEC.	TION VI	I - SPILL	OR LEAK PROC	EDURES
	EN IN CASE MATER				
•					
Wipe up sp	ill, remove r	esidue	with sol	vent-moistened	d rag.
WASTE DISPOSAL	METHOD				
	05.07101		COECIAL	PROTECTION IN	NEORMATION
			SPECIAL	THOTEGING:	
RESPIRATORY PE	OTECTION (Specify				I SPECIAL
VENTILATION	LOCAL EXHAUS	Ť			SPECIAL
	MECHANICAL (General)	:1-4:	recommended.	OTHER
PROTECTIVE GLO		il vent	llation	EVE PROTECTIO	N
		· · · · · · · · · · · · · · · · · · ·			
OTHER PROTECT	IVE EQUIPMENT				
				ECIAL PRECAU	TIONS
Use ordina:	o be taken in Hai	noling A care i	n handli	ng Gloves an	d/or safety glasses may be
appropriat	e depending of	n parti	cular ap	plication.	described the control of the control
OTHER PRECAU	TIPNS.			ressively sens	itized to glycidyl ethers(Epo)
Occasional	individuals i	may bec	TOme DIOR	TASSTANT SAIR	

PAGE (2)

Consult a physician if allergenic symptoms develop.

Form OSHA-20 Rev. May 72